

TEST REPORT

Report No.: B4430.01-801-44

Rendered to:

AMERICAN SKYLITES
Arlington, Texas

PRODUCT TYPE: Thermally Broken Curb Mount Prismatic Double Dome Skylight **SERIES/MODEL**: TCM – Prismatic - FG

SPECIFICATION: Occupational Safety and Health Administration/U.S. Department of Labor Regulations (Standards- 29 CFR)- 1910.23(e)(8).

 Architectural Testing

Test Report No.: B4430.01-801-44

Report Date: 11/08/11

Test Record Retention End Date: 11/08/15

Page 1 of 4

1.0 Report Issued To: American Skylites

525 113th Street

Arlington, Texas 76011

2.0 Test Laboratory: Architectural Testing, Inc.

2865 Market Loop

Southlake, Texas 76092

(817) 410-7202

3.0 Project Summary:

3.1 Product Type: Thermally Broken Curb Mount Prismatic Double Dome Skylight

3.2 Series/Model: TCM - Prismatic - FG

3.3 Compliance Statement: Results obtained are tested values and were secured by using the designated test method(s).

3.4 Test Dates: 11/08/2011 - 11/08/2011

3.5 Test Location: Architectural Testing, Inc. test facility in Southlake, Texas.

3.6 Test Sample Source: The test specimen was provided by the client. Representative samples of the test specimen will be retained by Architectural Testing for a minimum of four years from the test completion date.

3.7 Drawing Reference: The test specimen drawings have been reviewed by Architectural Testing and are representative of the test specimen(s) reported herein. Test specimen construction was verified by Architectural Testing per the drawings located in Appendix A. Any deviations are documented herein or on the drawings.

3.8 List of Official Observers:

<u>Name</u> <u>Company</u>

Michael Garcia American Skylites

Tony Brown Architectural Testing, Inc.

4.0 Test Specification(s):

Occupational Safety and Health Administration/U.S. Department of Labor Regulations (Standards- 29 CFR) - 1910.23(e)(8).

A 200 lbf weight, fabricated from a bag filled with sand, was placed on the center of the skylight for a minimum of 60 seconds. The bag was removed and the test unit was inspected for any signs of damage or failure. The bag was then dropped from varying heights above the skylight starting at 1', continuing to 6'. The highest impact load resulting in damage was recorded.



Architectural Testing

Test Report No.: B4430.01-801-44

Report Date: 11/08/11

Test Record Retention End Date: 11/08/15

Page 2 of 4

5.0 Test Specimen Description:

5.1 Product Sizes:

Overall Area:	Width		Height	
3.9 m ² (41.6 ft ²)	millimeters	inches	millimeters	inches
Overall size	1549	61	2464	97
Curb	1530	60-1/4	2445	96-1/4
Mounting ring	1562	61-1/2	2477	97-1/2

5.2 Frame Construction:

Frame Member	Material	Description
All members	Aluminum	Custom extruded, thermally broken, mill finish

	Joinery Type	Detail
All corners	Mitered & welded	Welded along top face & side face at corner

5.3 Mounting Ring Construction:

Mounting Ring Member	Material	Description
All members	Aluminum	Custom extruded, mill finish

	Joinery Type	Detail
All corners	Mitered & welded	Welded along top face & side face at corner

5.4 Weatherstripping: No weatherstripping was utilized.

5.5 Glazing:

Glazing Type	Interior Lite	Exterior Lite	Glazing Method
Double Dome	1/8" white acrylic	1/8" clear polycarbonate	Interior dome glazed with sealant tape along frame, exterior dome glazed with sealant tape along interior dome.

Logation	Quantity	Daylight Opening		Glazing	
Location	Quantity millimeter		inches	Bite	
Fixed skylight	1	1461 x 2375	57-1/2 x 93-1/2	3/4"	



Test Report No.: B4430.01-801-44

Report Date: 11/08/11

Test Record Retention End Date: 11/08/15

Page 3 of 4

6.0 Installation:

The specimen was installed onto a Spruce-Pine-Fir wood curb. The exterior perimeter of the frame was sealed with sealant at the curb.

Location	Anchor Description	Anchor Location
Frame to curb	#8 x 1-5/8" drywall screws	3" from corners, 12" o.c. thereafter
Mounting ring	#8 x 3/8" stainless steel screws	3" from corners, 12" o.c. thereafter
to frame	#0 x 3/0 Stanness steel screws	3 Hom corners, 12 o.c. thereafter

7.0 Test Results: The results are tabulated as follows:

7.1 OSHA Safety Test

Test	Load Location	Results
200 lbf	Center of dome	No visible damage

Note: The 200 lbf weight was gently applied perpendicular to the center of dome. After 60 seconds of rest time, there was no visible damage to skylight.

7.2 OSHA Safety Drop Test

Test Method	Load Location	Results
200 lbf-ft (1' drop height)	Inset 1" at center of longest edge	No visible damage
400 lbf-ft (2' drop height)	Inset 1" at center of longest edge	No visible damage
600 lbf-ft (3' drop height)	Inset 1" at center of longest edge	No visible damage
800 lbf-ft (4' drop height)	Inset 1" at center of longest edge	No visible damage
1000 lbf-ft (5' drop height)	Inset 1" at center of longest edge	No visible damage
1200 lbf-ft (6' drop height)	Inset 1" at center of longest edge	No visible damage



Test Report No.: B4430.01-801-44

Report Date: 11/08/11

Test Record Retention End Date: 11/08/15

Page 4 of 4

The service life of this report will expire on the stated Test Record Retention End Date, at which time such materials as drawings, data sheets, samples of test specimens, copies of this report, and any other pertinent project documentation, shall be discarded without notice.

If test specimen contains glazing, no conclusions of any kind regarding the adequacy or inadequacy of the glass in any glazed test specimen(s) can be made. This report does not constitute certification of this product nor an opinion or endorsement by this laboratory. It is the exclusive property of the client so named herein and relates only to the specimen(s) tested. This report may not be reproduced, except in full, without the written approval of Architectural Testing, Inc.

For ARCHITECTURAL TESTING, Inc.

Tony Brown	Andy Cost
Technician	Laboratory Manager

TB:hd


Attachments (pages): This report is complete only when all attachments listed are included. Appendix-A: Drawings (1)

This report produced from controlled document template ATI 00514, issued 02/28/11.

Test Report No.: B4430.01-801-44 Report Date: 11/08/11 Test Record Retention End Date: 11/08/15


Appendix A

Drawings



Test sample complies

_	and a second distribution of the second seco	
Report# 134430	Deviations :	
) >_ ~	<u>are p</u> oted.	s with these details



CLEXE WHITE

97Y:

QTY: QTY: 9TY:

OD CURB = OD CURB =

 \times

525 113th STREET ARLINGTON, TEXAS 76011 Phone 800.772.7401 Fax 800.445.7282

an: